INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1	NAME					
	HISTORIC					
_	AND/OR COMMON					
		ROWHOUSE				
2	LOCATION					
	STREET & NUMBER	806-808 West Lan	vale Street			
	CITY, YOWN	0-147	\$ \$6.000 (\$ \$4.000)	CONGRESSIONAL DISTRI	СТ	
		Baltimore	VICINITY OF		55:01	
	STATE	Maryland		COUNTY		
3	CLASSIFICAT	TION				
	CATEGORY OWNERSHIP STATUS		STATUS	S PRESENT USE		
		_PUBLIC	LOCCUPIED	AGRICULTURE	_MUSEUM	
		ZPRIVATE	_UNOCCUPIED	COMMERCIAL	PARK	
		_BOTH	_WORK IN PROGRESS	EDUCATIONAL	-VARIVATE RESIDENCE	
	SITE	PUBLIC ACQUISITION	ACCESSIBLE	ENTERTAINMENT	RELIGIOUS	
		_IN PROCESS	_YES: RESTRICTED	GOVERNMENT	SCIENTIFIC	
	15U (4)RPST0163 II		CH THE SHIP IS THE TANK TO THE TOTAL			
	-	BEING CONSIDERED	YES: UNRESTRICTED NO	INDUSTRIAL MILITARY	TRANSPORTATION	
	OWNER OF P		a n	Telephone #:		
	STREET & NUMBER					
	CITY, TOWN		VICINITY OF	STATE , Z	ip code	
5	LOCATION O	F LEGAL DESCR		Liber #:		
	COURTHOUSE.					
	REGISTRY OF DEEDS, ETC.	Records Office	Room 601	Folio #:		
	STREET & NUMBER	Baltimore City (Courthouse			
	CITY, TOWN	Baltimore		STATE Mary	land 21202	
6	REPRESENTA	ATION IN EXIST	ING SURVEYS	<u>2</u>		
	TITLE	City of Baltimore Neighborhood Survey				
	DATE	1978FEDERALSTATECOUNTY X_LOCAL				
DEPOSITORY FOR SURVEY RECORDS Commission foe Historic and Architectural Preservat				ation		
	CITY, TOWN	Baltimore		STATE Mary	land 21202	

7 DESCRIPTION

CONDITION

CHECK ONE

CHECK ONE

_EXCELLENT

__DETERIORATED

__UNALTERED

_ORIGINAL SITE

MOVED

_GOOD

_RUINS

_ALTERED

DATE____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The semi-detached house is two bays wide and three stories high. The foundation and first story facades are painted brick. Fenestration is symmetrical and proportional throughout the building facade. The roof is flat. To the right of the facade four concrete steps lead to the painted wood floor of the porch. The flat, wooden porch roof is supported by three round columns which are covered in painted formstone. Decorative painted wood molding has been applied to the porch roof. A simple, wrought iron railing to either side of the steps extends across the front and right side of the porch.

To the right the first story facade is punctuated by a flat window Jouble hung with one over one lights and accompanied by a painted wood sill and painted half arched brick lintel. To the left of the window the facade is punctuated by a flat wood door surmounted by a flat single light transom and painted brick half arched lintel. Both the second and third story facades are punctuated by two flat windows double hung with one over one lights and accompanied by painted wood sills. The lintels are obscured by formstone which decorates both upper story facades.

8 SIGNIFICANCE


SPECIFIC DATES			BUILDER/ARCHITECT		
	_1900-	COMMUNICATIONS	_INDUSTRY _INVENTION	POLITICS/GOVERNMENT	_OTHER (SPECIFY)
	¥1800-1899	COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	_TRANSPORTATION
	_1700-1799	ART	ENGINEERING	MUSIC	_THEATER
	_1600-1699	ARCHITECTURE	EDUCATION	_MILITARY	_SOCIAL/HUMANITARIAN
	_1500-1599	_AGRICULTURE	ECONOMICS	LITERATURE	_SCULPTURE
	_1400-1499	_ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	_SCIENCE
	PREHISTORIC	ARCHEULUGY-PREHISTORIC	_COMMUNITY PLANNING	_LANDSCAPE ARCHITECTURE	RELIGION
	PERIOD	AF	REAS OF SIGNIFICANCE CH	OF SIGNIFICANCE CHECK AND JUSTIFY BELOW	

STATEMENT OF SIGNIFICANCE

c.1865

This structure facing the Upton Mansion on Lanvale Street is c.1865, generally during Upton's early stages of urbanization. Both houses have been altered through the use of formstone, although the original brick construction is noticeable on the first floor. The cornice and a parapet wall conceal a gabled roof perpendicular to the street as shown of the Sachse air view 1869.

B-2979 806-808 W. Lanvale Street Block 0392 Lots 054-055 Baltimore City Baltimore West Quad.





8-2979 366 - 808